

Kaagapay ng Komunidad sa Maginhawang Pamumuhay

PURCHASE ORDER

Supplier: P.O. No.: 2024-04-081 MAN-AR AUTO REPAIR SHOP ~ 2332 ROXAS BLVD., BRGY. 13 ZONE 4, PASAY CITY Date: 04/25/2024 Address: TIN: P.R. No.: 2024-03-279 ~ 232-094-890-0000 Mode of Procurement: Negotiated Procurement Date: 03/13/2024 Gentlemen: Please furnish this Office the following articles subject to terms and conditions contained herein. Place of Delivery: 8737 BDO PLAZA PASEO DE ROXAS MAKATI CITY Delivery Term: FOB Destination Payment Term: 15 working days upon complete Date of Delivery: 7 CALENDAR DAYS UPON RECEIPT OF APPROVED PO delivery Quantity **Unit Cost** Amount Stock No. Unit Description Repair - Motor Vehicle-7 L Motor Oil 63,000.00 63,000.00 A-000-694 Lot 1 pc Oil Filter pc Air Filter 1 pc Fuel Filter set Front Brake Pad pc A/C Blower Motor Assembly pc Front Expansion Valve Funded by: pc Rear Expansion Valve BUR # M-242-0884 pc Drier (Aluminum) 16 pcs O-ring Dated: 05/02/2022 2 lot Freon 134A (Dual) 8 onz A/C Oil 1 pc A/C Cabin Filter 2 unit Solvent A/C Compressor Assembly (Tentative) pc Front Cooling Coil (Tentative) 1 pc 1 pc Rear Cooling Coil (Tentative) 4 pes Expansion Valve Bolt (Tentative) Aircon Works Pulldown evaporator front and rear for general cleaning and leak test. Remove and replace a/c blower motor assembly, front expansion valve, rear expansion valve, a/c cabin filter, drier element and orings. Pump all lines, dehydrates system, add a/c oil. Recharge freon. Change Oil Remove and replace motor oil and filter Remove and replace air filter and fuel filter. Check Timing and idling. Brake System Remove and replace front brake pads. Adjust rear brake shoe. Pulldown and re-install front rotor disc to reface. Machine Shop Reface fron rotor disc. Toyota Innova SHJ895 Total Amount in Words: SIXTY THREE THOUSAND AND 00/100 ONLY 63,000.00

| nforme: | Very truly yours, |
|---|--|
| Signature over Printed Name of Supplier | ATTY. TRISTAN FREDERICK L. TRESVALLES Authorized Official St. 1000 |
| Date Date | |